

JOB  
ADDRESS

1543 E 91 ST

OWNER

EARTHQUAKE  
DAMAGE

①

LARGE CRACKS

IN THE EXTERIOR

PLASTER (close  
TO BASE  
OF WALL)

EAST, NORTH,  
AND WEST  
WALLS.

HOUSE WAS

NOT POSTED

UNSAFE.

4-6-94 J. Rodgers

DATE

INSPECTOR'S SIGNATURE



COUNTY OF LOS ANGELES  
DEPARTMENT OF PUBLIC WORKS  
BUILDING AND SAFETY DIVISION

INVESTIGATION REPORT

LOCATION OF PROBLEM 1543 E. 91st Street

LOCALITY \_\_\_\_\_

DESCRIPTION OF PROBLEM Earthquake damage

REQUESTED BY \_\_\_\_\_ PHONE \_\_\_\_\_

ADDRESS \_\_\_\_\_

RECEIVED BY Helen Gruyer DATE 4/1/94

REFERRED TO \_\_\_\_\_ DATE \_\_\_\_\_

REPORT OF INVESTIGATION LARGE CRACKS IN THE  
EXTERIOR PLASTER WALLS (EAST  
NORTH, WEST WALLS)  
HOUSE WAS NOT POSTED  
UNSAFE

INVESTIGATOR C. ROYCE TITLE PLC INSPECTOR DATE 4/6/94

COPY SENT TO \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

REPORT PHONED TO \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

1/75